

Star of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Report Data October 25, 2006

Supervisor

Report Date: October 25, 2006

Mine Name: Travertine #1	Permit number: M0230042		
Operator Name: BEG Resources	Date: October 19, 2006		
	Time: 2:00-2:30 PM		
Inspector(s): Paul Baker			
Other Participants: None			
Mine Status: Reclaimed	Weather: Mostly clear, 50s		
Elements of Inspection	Evaluated	Comment	Enforcement
 Permits, Revisions, Transfer, Bonds Public Safety (shafts, adits, trash, signs, highwalls) Protection of Drainages / Erosion Control Deleterious Material Roads (maintenance, surfacing, dust control, safety) Concurrent Reclamation 			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			

Purpose of Inspection:

8. Water Impoundments

10. Revegetation11. Air Quality12. Other

9. Soils

I wanted to check the vegetation and see how it was progressing.

Inspection Summary:

10. Revegetation

I measured perennial and native annual vegetation cover in the reclaimed area and in an adjacent undisturbed area. I obtained cover values of 3.45 percent in the reclaimed area and 13.4 percent in the undisturbed area. Dominant species in the reclaimed area were crested wheatgrass, intermediate wheatgrass, and blazing star. Nearly all the perennial vegetation in the undisturbed area was sagebrush.

Most of the reclaimed area had surprisingly few weeds, but there was a south-facing slope toward the north side of the mine with a lot of Russian thistle and some other annuals. This area also had a lot of blazing star.

Conclusions and Recommendations:

The plan states:

"Successful revegetation is achieved when 25% (70% X 35%) ground cover is achieved over all reclaimed areas."

M0230042

Inspection Date: October 19, 2006; Report Date: October 23, 2006

Page 2 of 2

The reclaimed area does not meet this revegetation success standard, and I do not expect it to meet this standard without remedial work.

There are portions of the reclaimed area, especially toward the west side, with enough vegetation that no additional work should be needed. Except on the outslopes, I found very few perennials on the north and east parts of the area.

If the site had a lot of cheatgrass, I would be reluctant to recommend reseeding, but Russian thistle is not overly competitive. I believe the operator should re-roughen and reseed those areas where there is little perennial cover.

Inspector's Signature

21 B M Date: 10/30/06

PBB:pb

cc:

Bob Steele, Fillmore BLM

 $P:\GROUPS\MINERALS\WP\M023-Juab\M0230042-Begtravertine\nspections\ns-10192006.doc$